	Туре	Hits	Search Text	DBs	Time Stamp
1	IS&R	526	(164/4.1).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2007/08/16 11:41
2	IS&R	183	(164/154.1).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2007/08/16 11:36
3	IS&R	49	(164/450.2).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2007/08/16 11:36
4	IS&R	2	(("3160009") or ("3303537")).PN.	USPAT	2007/08/16 11:40
5	BRS	16	("3303537").URPN.	USPAT	2007/08/16 11:40
6	BRS	2	("3160009").URPN.	USPAT	2007/08/16 11:41
7	IS&R	5259 7	("164").CLAS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2007/08/16 11:41
8	BRS	15	S7 and (die adj cast\$3) near100 (mold or die) near100 (temperature near10 (measur\$3 or detect\$3))	US-PGPUB; USPAT; EPO; JPO; DERWENT	2007/08/16 11:49
9	BRS	36	(die adj cast\$3) near100 (mold or die) near100 (temperature near10 (measur\$3 or detect\$3))	US-PGPUB; USPAT; EPO; JPO; DERWENT	2007/08/16 11:50

	Туре	Hits	Search Text	DBs	Time Stamp
10	BRS	72	(die adj cast\$3) near100 (mold or die) and (temperature near10 (measur\$3 or detect\$3)) and radiation	US-PGPUB; USPAT; EPO; JPO; DERWENT	2007/08/16 11:51
11	BRS	8	(die adj cast\$3) near100 (mold or die) and (temperature near10 (measur\$3 or detect\$3)) near100 radiation	US-PGPUB; USPAT; EPO; JPO; DERWENT	2007/08/16 11:51
12	BRS	83	(mold or die) near50 (measur\$3 or detect\$3) near100 temperature near100 radiation	US-PGPUB; USPAT; EPO; JPO; DERWENT	2007/08/16 11:53
13	BRS	3	(mold or die) near50 (measur\$3 or detect\$3) near100 temperature near100 radiation near200 (air or blow\$3)	US-PGPUB; USPAT; EPO; JPO; DERWENT	2007/08/16 11:53
14	BRS	6	(mold or die) near50 (measur\$3 or detect\$3) near100 radiation near200 (air or blow\$3)	US-PGPUB; USPAT; EPO; JPO; DERWENT	2007/08/16 11:54

	Туре	Hits	Search Text	DBs	Time Stamp
15	BRS	7	(mold or die) near50 (measur\$3 or detect\$3 or monitor\$3) near100 radiation near200 (air or blow\$3)	US-PGPUB; USPAT; EPO; JPO; DERWENT	2007/08/16 11:54
16	BRS	7	(mold or die) near200 (measur\$3 or detect\$3 or monitor\$3) near200 radiation near200 (air or blow\$3)	US-PGPUB; USPAT; EPO; JPO; DERWENT	2007/08/16 11:55
17	BRS	162	(mold or die) near200 (measur\$3 or detect\$3 or monitor\$3) near200 (air near10 (blow\$3 or compress\$2))	US-PGPUB; USPAT; EPO; JPO; DERWENT	2007/08/16 11:55
18	BRS	22	(mold or die) near200 (measur\$3 or detect\$3 or monitor\$3) near200 (temperature or radiation) near200 (air near10 (blow\$3 or compress\$2))	US-PGPUB; USPAT; EPO; JPO; DERWENT	2007/08/16 11:57

	Туре	Hits	Search Text	DBs	Time Stamp
19	BRS	657	(mold or die) same surface same (measur\$3 or detect\$3 or monitor\$3) same (temperature or radiation) and (air near10 (blow\$3 or compress\$2))	US-PGPUB; USPAT; EPO; JPO; DERWENT	2007/08/16 11:58
20	BRS	79	(mold or die) same surface same (measur\$3 or detect\$3 or monitor\$3) same (temperature or radiation) same (air near10 (blow\$3 or compress\$2))	US-PGPUB; USPAT; EPO; JPO; DERWENT	2007/08/16 11:59
21	BRS	38	die same surface same (measur\$3 or detect\$3 or monitor\$3) same (temperature or radiation) same (air near10 (blow\$3 or compress\$2))	US-PGPUB; USPAT; EPO; JPO; DERWENT	2007/08/1 <u>6</u> 11:59
22	BRS	1	die same surface same (measur\$3 or detect\$3 or monitor\$3) same (temperature same radiation) same (air near10 (blow\$3 or compress\$2))	US-PGPUB; USPAT; EPO; JPO; DERWENT	2007/08/16 11:59

	Туре	Hits	Search Text	DBs	Time Stamp
23	BRS	5	die same surface same (measur\$3 or detect\$3 or monitor\$3) same (temperature same radiation) and (air near10 (blow\$3 or compress\$2))	US-PGPUB; USPAT; EPO; JPO; DERWENT	2007/08/16 11:59